E ink

Quick start guide for THOR 4.37˝ E Ink Spectra ™ 3100

Demo Kit Hardware Description

Button	Function
SW1	Reset
SW2	Next image
SW3	White image
SW4	Previous image
SW5	White/Black/Red/Yellow image

## Assembly and Operating Instructions

① Attach the panel to THOR

② Connect the mini-USB to THOR

③ Connect the mini-USB to USB power

④ Press SW2 Next image

⑤ Press SW3 White image

⑥ Press SW4 Previous image

⑦ Press SW5 White/Black/Red/Yellow image

Disassembly Instructions

① Disconnect the mini-USB from USB power

② Disconnect the mini-USB from THOR

③ Detach the panel from THOR

We Make Surfaces Smarter ™