Quick start guide for Hulk 5.65″ E Ink Gallery Palette ™ 4000

## Demo Kit Hardware Description

| Button	Function
SW1	Reset
SW2	Next image
SW3	White image
SW4	Previous image
SW5	Slide Show Mode

Assembly and Operating Instructions

① Attach the 5.65" panel to Hulk

② Connect the mini-USB to Hulk

③ Connect the mini-USB to USB power

④ Press SW2 Next image

⑤ Press SW3 White image

⑥ Press SW4 Previous image

⑦ Press SW5 Slide Show Mode

Disassembly Instructions

① Disconnect the mini-USB from USB power

② Disconnect the mini-USB from Hulk

③ Detach the 5.65" panel from Hulk