

User Guide Standards

Salt System Board

For 31.2["] monochrome ePaper Display Application



Table of Contents

Tab	le o	f Cont	ents	.2
	1	Introduction		
	2	Hard	ware Guide	.2
	3	Usage		
		(1)	Uploading image	3
		(2)	Procedure is as following	3
	4	Cont	act Information	.9
	5	Lega	I Information	.9

1 Introduction

E Ink's 31.2" monochrome evaluation kit Salt is intended to highlight the features and benefits of the 31.2" monochrome EPD display. This document will provide details on how to use the Salt to display.

To be advised that EVK is not suitable to use in outdoor as a product because if the condense water occur on EVK, it might cause the short circuit to damage the board.



2 Hardware Guide

This section describes the hardware setup of the Salt evaluation kit for 31.2" monochrome.

This demo kit contains the following:

- Salt System Board
- FFC cable*5
- Adapter 12V 5A



Module Name	Description
Salt board	TCON
Transfer board	Bridging of panel and salt board
FFC	Connect for 31.2" monochrome panel and Salt board

3 Usage

(1) Uploading image

When connected to a PC, the interface, AP, could upload pictures in BMP(24bit) or JPG(24bit) format from PC to Salt through Micro USB.

Note : the picture format needs to be fit the resolution of EPD.

(2) Procedure is as following

Connection

- (1) Salt connected to PC.
- (2) Connect 31.2" monochrome EPD to Salt. (Tcon board + transfer board)
- (3) Connect Micro USB to Salt.
- (4) Run "T1000_Windows_AP.exe" software.
- (5) Click "Connect" button to make sure the software has connected to Physical Drive.

Fink T1000 Demo AP v.5.0.1.8		×
EnMirror En_4: Connect EnFlip EnCFA Rotat	2_Flip A_RGB565 te_CCW_90	Engineer Features About OK Cancel
Generic Storage RamDisc 1.00 Starched 1 Disks i T1000. G A Image Buffer Address H = 0x 0 G A Image Buffer Address L = 0x 0 F W Version = v.000.000.053 S gnature = 8957 Fanel Width = 1440 Fanel Height = 2560 I hage Buffer Address = 0x430958 Vaveform: (3 Modes, 29 Temperature Segments)	Succes	Refresh Upgrade Image Firmware(*.bin) wbf Address(hex) Image Waveform(*.wbf) 900000 Image Mode Centralize Image Mode Repeat SlideShow Time Interval(Secs) Start Start Load Image and Display X X Y Start Start Uddth Height End Mode 2 Image In Convert to 3 color AutoSet Open File Display Image Inclr/White Set Full Panel
Clear	v	

Software connected to Physical Drive

- VCOM Set/Get
 - (1) VCOM to set by the AP is currently not valid.
 - (2) Currently VCOM is adjusted by variable resistor(VR1), recommend to use plastic screwdriver.
 - (3) VCOM voltage is measured by TP_VCOM1.



Set/Get VCOM

• Display EPD operation (single image mode)

- (1) Click "Open File.." to load image.
- (2) Edit display area and select waveform mode to display current image.
- (3) Click "Display" to show selected image on EPD.
- (4) In the begin of the connection, in order to minimize artifact, to select "EnClrWhite" option and Start Mode/End Mode select 0, click "Display"

button, the EPD should show with white picture.

Notice : The "EnClrWhite" is only allow to use in the beginning of the connection.

EnMirror E	n 42 Flip	About	
connect	CFA_RGB565	Engineer Features	
R	otate_CCW_90		Cancel
Generic Storage RamDisc 1.00			•
		Refresh	Upgrade
in T1000.	<u>^</u>	Firmware(*.bin) wbf Address(hex)	
CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L= 0x 0			Auto Reset
FW Version = v.002.002.053 Signature = 8957			
Panel Width = 1440 Panel Height = 2560		Display Mode	entralize
Image Buffer Address = 0x430960 Waveform: (6 Modes, 14 Temperature Segments)		C SlideShow Time Interval(Secs)	epeat
- 1828		n	Start
	• • • • • • • • • • •	-Lond Image and Display	
	e	X Y Start	Mode
		Width Height End f	Mode 2
Constant of the stand of the st	UNAS SANDYANS SANDYANA da baha baha Dénas 2017-012-014 2012-02-000	1440 2560 2	
		En Convert to 3 color	oSet
10 ² 2 m		Open File	1
	in all all all all all all all all all al		
	du Indu Rong 2002 Rijeg -	I EnClrWhite Set Full Pa	
##254 Kondy to see the state of a		Display	
Clear		1	
T1000 Demo AP v 5.0.1.8		-	×
ж T1000 Demo AP v.5.0.1.8			×
* T1000 Demo AP v.5.0.1.8	42_Flip	Fonineer Features	ок
T1000 Demo AP v.5.0.1.8 EnMirror EnFlip En	_42_Flip CFA_RGB565 ptate_CCW_90	About Engineer Features	OK Cancel
T1000 Demo AP v.5.0.1.8	_42_Flip CFA_RGB565 otate_CCW_90	Engineer Features About	OK Cancel
T1000 Demo AP v.5.0.1.8 Connect Conn	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh	OK Cancel
	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh (* Firmware(*.bin) wbf Address(hex)	OK Cancel
	_42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh G Firmware(*.bin) Wbf Address(hex) Waveform(*.wbf)	OK Cancel Upgrade Auto Reset
t T1000 Demo AP v.5.0.1.8 Connect Connect EnFlip Connect Searched 1 Disks in T1000. CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 FW Version = v.000.000.053 Signature = 8957	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh © Firmware(*.bin) wbf Address(hex) - © Waveform(*.wbf) 90000	OK Cancel Vpgrade Auto Reset
T1000 Demo AP v.5.0.1.8	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 900000 Display Mode	OK Cancel Upgrade Auto Reset
	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 Display Mode MulEngine SildeShow Time Interval(Secs)	OK Cancel
the T1000 Demo AP v.5.0.1.8 EnMirror EnMirror EnMirror EnMirror EnFlip	42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 C MulEngine C SlideShow Time Interval(Secs) MulEngine C SlideShow	OK Cancel Upgrade Auto Reset
Image Buffer Address H = 0x 0 CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 Panel Width = 1440 Panel Width = 1440 Panel Buffer Address = 0x430958 Image Buffer Address = 0x430958 Decode Image File: D: 0_signage EPD BH\312\KKBW Width = 1440 height = 2560 Decode Image File: D: 0_signage EPD BH\312\KKBW Height = 1250 Decode Image Time = 717	_42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 MulEngine SideShow Time Interval(Secs) Load Image and Display	OK Cancel Upgrade Auto Reset
T1000 Demo AP v.5.0.1.8	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 900000 MulEngine C MulEngine C MulEngine Load Image and Display X Y Start 0 0 2 2 2 2 2 2 2 2 2 2 2 2 2	OK Cancel Vpgrade Auto Reset entralize epeat Start
T1000 Demo AP v.5.0.1.8	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*,bin) Display Mode MulEngine Display Mode MulEngine Load Image and Display K Y Start 0 0 2 V	OK Cancel Upgrade Auto Reset Auto Reset
T1000 Demo AP v.5.0.1.8 EnMirror connect EnFlip Generic Storage RamDisc 1.00 Searched 1 Disks in T1000, CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address S = 0x 0 FW version = v.000.000.053 Signature = 9957 Panel Width = 1440 Panel Height = 2560 Image Buffer Address = 0x430958 Width = 1440 Panel File: D: V0_signage EPD B/H\312\KEBY Width = 1440 Pecode Image Time = 717 Sending Image Time = 717 Send Image Time = 141	_42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) Waveform(*.wbf) 900000 MulEngine C MulEngine C MulEngine C MulEngine C MulEngine C MulEngine C MulEngine C	OK Cancel Upgrade Auto Reset entralize epeat Start Mode Mode
T1000 Demo AP v.5.0.1.8 EnMirror connect EnFlip Generic Storage RamDisc 1.00 Searched 1 Disks in T1000. CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address = 0x 400 Width = 1440 Panel Height = 2560 Decode Image File: D: \0_signage EVPD @/f\312\&CKBYW Width = 1440 height = 2560 Decode Image File: D: \0_signage EVPD @/f\312\&CKBYW Width = 1440 Sending Image File to Device Send Image Time = 717 Sending Image Time = 141	42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 C MulEngine C SlideShow Time Interval (Secs) Load Image and Display Load Image an	OK Cancel Upgrade Auto Reset Auto Reset
T1000 Demo AP v.5.0.1.8 connect connect Generic Storage RamDisc 1.00 Searched 1 Disks in T1000, CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address L = 0x 0 FW Version = v.000.000.053 Signature = 8957 Panel Width = 1440 Panel Height = 2560 Image Buffer Address = 0x430958 Decode Image File: D·V_signage VEPD Im Fils12 \kefter V Width = 1440 height = 2560 Decode Image File: D·V_signage VEPD Im Fils12 \kefter V Width = 1440 height = 1250 Decode Image File: D·V_signage VEPD Im Fils12 \kefter V Sending Image File to Device Sending Image File to Device. Send Image Time = 141	_42_Flip CFA_RGB565 .otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 MulEngine C MulEngine Display Mode C MulEngine Load Image and Display C mulengine C mul	OK Cancel Upgrade Auto Reset Auto Reset
T1000 Demo AP v.5.0.1.8 connect connect Generic Storage RamDisc 1.00 Searched 1 Disks in T1000. CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 FW Version = v.000.000.053 Signature = 8957 Panel Width = 1440 Panel Height = 2560 Image Buffer Address = 0x430958 Decode Image File: D: \0_signage \EPD Ar\312\KEBY width = 1440 height = 2560 Decode Image File: D: \0_signage \EPD Ar\312\KEBY Sending Image File to Device Send Image Time = 717 Sending Image File to Device Send Image Time = 141	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 90000 MulEngine MulEngine C MulEngi	OK Cancel
T1000 Demo AP v.5.0.1.8 connect connect EnPlip Generic Storage RamDisc 1.00 Searched 1 Disks in T1000. CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address L = 0x 0 FW Version = v.000.000.053 Signature = 8957 Panel Height = 1240 Decode Image File: D: \0_signage\EPD Implies Width = 1440 Pheight = 2560 Decode Image File: D: \0_signage\EPD Implies Send Image Time = 717 Send Image Time = 141 Succes	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh Firmware(*.bin) wbf Address(hex) Waveform(*.wbf) 900000 MulEngine MulEngine C MulEng	OK Cancel Upgrade Auto Reset Entralize epeat Start Mode Solution
T1000 Demo AP v.5.0.1.8 EnMirror connect EnFlip Generic Storage RamDisc 1.00 Searched 1 Disks in T1000. CFA Image Buffer Address H = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address L = 0x 0 CFA Image Buffer Address = 0x 430958 Image Buffer Address = 0x430958 Image Buffer Address = 0x430958 Decode Image File: D:\0_signage\EPD () H\312\\XERW\ Width = 1440 height = 2560 Decode Image Time = 717 Send Image Time = 141 Succes	_42_Flip CFA_RGB565 otate_CCW_90	About Engineer Features Refresh • Firmware(*,bin) wbf Address(hex) • Waveform(*,wbf) 900000 • Waveform(*,wbf) 900000 • SideShow Time Interval(Secs) • Load Image and Display • X Y • Start • 0 • 0 • 2 • Width • Height • 11440 • 2560 • 2 • En Convert to 3 color • Auto • Display • EnClrWhite • Set Full Pa • Display • Display • EnClrWhite • Set Full Pa • Display • EnClrWhite • Display • EnClrWhite • Set Full Pa • Display • EnClrWhite • Set Full Pa • Display • EnClrWhite • Set Full Pa • Display • Display • EnClrWhite • Open File • Display • Display • Open File • Display • Display • Open File • Display • Open File • Display • Disp	OK Cancel Upgrade Auto Reset entralize epeat Start Mode Mode Start

Load image to Salt and display the image



Minimize artifact

• Display EPD operation (slide show mode)

- (1) Salt connected to PC.
- (2) Upload all images under the folder name as "SlideShowImages".
- (3) Set "Display Mode" and "Time Interval".
- (4) Select "SlideShow" option and click "Start" button.



Run slideshow

Other Features Description

- Firmware Update
 - (1) Salt connected to PC.
 - (2) Firmware and "T1000_Windows_AP.exe" in the same folder.
 - (3) Select the "Firmware" and click "Refresh" button and select the FW.
 - (4) Click "Upgrade" button to update FW.
 - (5) If update is success, please re-plug the power.(reset)

32inchBW_BX_V1.0.bin				
Refresh Firmware(*.bin) Waveform(*.wbf	wbf Address(hex) 900000	Upgrade		



- Waveform Update
 - (1) Salt connected to PC.
 - (2) Waveform and "T1000_Windows_AP.exe" in the same folder.
 - (3) Select the "Waveform" and click "Refresh" button and select the WF.
 - (4) Click "Upgrade" button to update WF.
 - (5) If update is success, please re-plug the power.(reset)

V220_C297_EE0501_ED312TT3C1_CTC.w	vbf 💌
Refresh C Firmware(*.bin) Waveform(*.wbf)	Upgrade

Select the Waveform

- Temperature Set/Get
 - (1) First Click "Engineer Features" button.
 - (2) Set/Get temperature value.
 - (3) Click "Execute" button to Set/Get temperature.
 - (4) Click "OK" button.

yg 📒
Register R/W OK RegAddr(Hex) Value(Hex) C Read Write Execute VComSetting (mV) C Power on C Power off C Power on with Set VCom Execute C Set VCom C Get VCom C Get VCom Memory Addr(Hex) Size(Hex) Dump Dump

Temperature Set/Get

Checkbox function explanation Each of the checkbox described above the AP has to be selected before you load an image using "Open File" button based on different firmware.

- (1) EnMirror : Select in 31.2" display, to Mirror image into Tcon image buffer.
- (2) EnFlip : Select in 31.2" display, to flip image into Tcon image buffer.
- (3) En_42_Flip : Select in 42" display, to flip left side of the 42" panel in gate scan direction.
- (4) EnCFA_RGB565 : Select it When using 31.2" CFA EPD.
- (5) Rotate_CCW_90 : Select in 31.2" display if image is landscape, Rotate counter clockwise 90 degrees.

EnMirror	En_42_Flip	
EnFlip	EnCFA_RGB565	
	Rotate_CCW_90	

Other Features

4 Contact Information

For more information, please visit

http://www.eink.com

For sales office addresses, please visit

http://www.eink.com/contact_sales.html

5 Legal Information

Definitions

The document is a draft version only. The content is still under internal review and subject to formal approval which may result in modifications or additions. E Ink does not give any representations or warranties as to the accuracy or completeness of information included herein and shall have no liability for the consequences of use of such information.

• Right to make changes

E Ink reserves the right to make changes to information published in this document, including without limitation specifications and product descriptions, at any time and without notice.

Suitability for use

Products described in this document are intended for development purposes only and comes without any warranty. E Ink accepts no liability for inclusion and/or use of E Ink products in commercial products or applications and therefore such inclusion and/or use is at the customer's own risk. In no event shall E Ink be liable for any direct, indirect, incidental, special, exemplary, or consequential damages (including, but not limited to, procurement of substitute goods or services; loss of use, data, or profits; or business interruption) however caused and on any theory of liability, arising in any way out of the use of the software.

Applications

Applications that are described herein for any of these products are for illustrative purposes only. E Ink makes no representation or warranty that such applications will be suitable for the specified use without further testing or modification.

• No offer to sell or license

Nothing in this document may be interpreted or construed as an offer to sell products that is open for acceptance or the grant, conveyance or implication of any license under any copyrights, patents or other industrial or intellectual property rights.

• Trademarks

Notice: All referenced brands, product names, service names, and trademarks are the property of their respective owners.

• Revision History

Version	Date	Pag	Description	Author
1.0	2019/8/14		Initial	Ryan